23rd July 1962]

Name of schemes.	*Remarks*
37 Mukkundram, Suralur, Chinnalam palli and Synagunta.	
38 Rangasamudram and Dakshina pathapalayam.	
39 Christianpet and Sallavoor	
40 Sampalli	
41 Ramapuram, etc., villages	
42 Additional loads at Ramalai	
43 Mudilampet and Kilvilachur villages.	
44 H.T. demand for tannery at Labbaimankuppam.	
45 Cholamur, Velampet	
46 Senji (additional loads)	
47 Additional loads at Ramapuram.	

APPENDIX II.

[*Vide* answer to starred question No. 531 on page 7.]

A.—The stage of various pond works in Erode taluk of Coimbatore district referred to above are furnished below :—

(1) *Pond near Karumanjirai.*—An estimate for Rs. 50,500 has been received from the Subdivisional Officer, Coimbatore, and it is under scrutiny in the Office of Executive Engineer (F.P.), Vellore.

(2) *Pond near Velliampathi village.*—An estimate for Rs. 16,600 was prepared by Food Production Division, Vellore But the Collector has not recommended the proposal as the lower down ayacutdars of Adhiyur taluk have objected to the formation of pond. Hence the estimate was not sanctioned.

(3) *Pond near Vettalapathy village.*—An estimate for Rs. 27,700 was prepared by the Executive Engineer (F.P.) Division, Vellore, and has been sent to the Collector for countersignature.

(4) *Pond near Neelagoundenpalayam.*—As estimate for Rs. 41,000 has been received from the Subdivisional Officer and is under scrutiny by the Food Production Division, Vellore.

(5) *Pond near Vepampalayam.*—Estimate has not been received from the Subdivisional Officer and he is being asked to report the present stage of the same.

(6) *Pond near Vettiankinar.*—An estimate for Rs. 24,100 has been countersigned by the Collector. Action is being taken by Executive Engineer (F.P.), Vellore Division, to get it administratively approved by Superintending Engineer (F.P.).

(7) *Pond near Enjampalayam.*—This refers to the work of formation of pond near Thingalore. An estimate was sanctioned for Rs. 30,600. Contract for the scheme will be finalized soon and the work started.

[23rd July 1962

(8) *Pond near Pappampalayam.*—This refers to formation of pond near Karapalayam Reddipalayam. An estimate for the work is awaited from the Subdivisional Officer. The Executive Engineer (F.P.), Vellore, has reminded the Subdivisional Officer.

(9) *Pond near Kizheripalayam.*—A revised estimate for Rs. 25,300 submitted to the Board of Revenue (F.P.) by the Superintending Engineer (F.P.) is under consideration of the Board of Revenue.

(10) *Pond near Gundumalainaickanur.*—An estimate for Rs. 10,900 was submitted to the Collector. The Collector did not agree to the proposal as it would affect the supplies to the lower down Punjai Dalavoipalayam tank. Hence the proposal has been dropped.

(11) *Pond near Sengalipalayam.*—The estimate is awaited from the Subdivisional Officer and he has been reminded by the Executive Engineer (F.P.), Vellore.

APPENDIX III.

[*Vide* answer to starred question No. 537 on page 9.]

Serial number and name of the scheme. (1)	*Estimated cost.* (2) (RUPEES IN LAKHS.)	*Present stage.* (3)
1 Constuction of an anicut across Pambar in Kilasapuram village in Thirumayam taluk.	2·33	Board has raised certain points for clarification regarding the scheme; the Chief Engineer awaits the Superintending Engineer's report in the matter.
2 Construction of an anicut acrosss Agniar near Pulavanagadu village in Alangudy taluk.	17·20	Remarks of the Board of Revenue on the revenue, financial and Grow More Food aspects of the scheme formulated by the Chief Engineer (Irrigation) are awaited.
3 Construction of an anicut across Korayar near Mullaiyar village in Kolathur taluk.	0·94	The Board of Revenue (Food Production) has been asked to report whether any lower down riparian rights will be affected by the implementation of the scheme; Board's report is awaited.
4 Construction of a head sluice and excavation of a right bank supply channel from the Heldsworth anicut across Vellar in Thirumayam taluk.	4·51	Board has raised certain points for clarification regarding the scheme; the Chief Engineer is awaiting the Superintending Engineer's report in the matter.

TAMIL NADU LEGISLATIVE ASSEMBLY ... ALONE TRIUMPHS